heal with LASER

How to Clean Your Laser Safety Glasses

Using Only Soapy Water

Rinse Glasses
1
Rinse glasses with warm water

2
Wash Gently
Use mild dish soap & soft fingers

3
Rinse Thoroughly
Rinse off all soap residue

4
Dry Carefully
Pat dry with a clean, soft cloth

UNIVET

univetlaser.com/5X7

Do not use alcohol based disinfectant